

SUPPLIER	BRAND	MODEL	CANNOT BE CHANGED	SOFTWARE UPGRADE REQUIRED	EURO COMPLIANT	REMARKS	
SG Solutions Limited	Sweda	SPAZIO UNO	X				
		Model 2135	X				
		S-100	X				
	Casio	FE-700	X				
		FE-2000	X				
		Tk-1200	X				
	Kabel	VJ-100			X		EEPROM replacement required – around Lm32 (excluding VAT).
VJ-200				X			
J.G. Systems Limited	Orgtechnica	OT811 Fiscal Printer			X		
		MINI 500.03 elka			X		
		MINI 600.04			X		
		MINI 700			X		
		MINI elka			X		
Rifatronix	Quorion	CR7157T			X		
		CR2010T			X		
		CR70 5T			X		
		CR30 T2			X		
		CR2500T			X		
		CR2000			X		
		Q-touch			X		
Forestals Appliances Limited	Siemens Nixdorf	ITALDATA CR 20	X				
		CR 15	X				
		CR 20	X				
Advanced Telecommunications Limited	Compass Data Systems	CDS 490T	X				
		CDS 490E	X				
		CR 400			X		
Electronic Products Limited	Omron	GR25	X				
		GR30	X				
		RS19	X				
		RS28	X				
		RS28TH	X				
		RS4000	X				
	Unisystem	Mini 500	X				
	RCH	Onda			X		
	CHD	2020			X		
	ARG	eSHOP			X		
Gozo Business Systems Limited	Siemens	Italdata CR15	X				
		Italdata CR20	X				
	RCH	Onda			X		
		Mizar			X		
		G3000			X		
		Nucleo			X		
Videosoft Computers Limited	Ditron	EU 200		X		EEPROM replacement required – estimate of Lm30 + VAT to update a machine.	
	Sapel	Sapel 2000		X			
H.L.S. Enterprises	Elzab	Jota		?		HLS still awaiting confirmation from its supplier of whether a modification is required. Indication that cost involved, however, no actual cost given.	
	Arcadia	6142		X		Lm10 including VAT per machine.	
	Digitax	ET807/TE	X				
	BMC	PS 2000				X	Lm10 including VAT per machine.
		AP 190	X				
		CR 280	X				
	Micrelec Electronics	Assini PRB			X		Lm10 including VAT per machine.
Caravel Limited	Ditron	EU128				Update that involves EEPROM reprogramming – standard fee of around Lm12-15.	
		EU200					
		EU300					
		EU1000					